







| BILL OF MATERIALS |     |                     |                |             |
|-------------------|-----|---------------------|----------------|-------------|
| ITEM              | QTY | DESCRIPTION         | MANUF.         | PART NUMBER |
| 1                 | 1   | BUTTONMATE ASSEMBLY | READY ROBOTICS | R-100103    |
| 2                 | 1   | GRIPPER ASSEMBLY    | READY ROBOTICS | R-101213    |
| 3                 | 1   | MANIFOLD ASSEMBLY   | READY ROBOTICS | R-101219    |
| 4                 | 1   | WISE ASSEMBLY       | READY ROBOTICS | R-101226    |
| 5                 | 1   | WISE ASSEMBLY       | READY ROBOTICS | R-101231    |




Pneumatic Block Diagram, Mill Tending

|                                                                                                                                                     |           |                      |                       |          |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------|-----------------------|----------|
| <br>READY Robotics<br>1080 Steelwood Rd.<br>Columbus, OH 43212 | SIZE<br>B | DO NOT SCALE DRAWING | DWG. NO.<br>PD-600009 | REV<br>- |
|                                                                                                                                                     |           |                      |                       |          |
| ISSUED                                                                                                                                              | SCALE N/A | SHEET 1 OF 2         |                       |          |



| BILL OF MATERIALS |     |                     |                |             |
|-------------------|-----|---------------------|----------------|-------------|
| ITEM              | QTY | DESCRIPTION         | MANUF.         | PART NUMBER |
| 1                 | 1   | BUTTONMATE ASSEMBLY | READY ROBOTICS | R-100103    |
| 2                 | 1   | GRIPPER ASSEMBLY    | READY ROBOTICS | R-101213    |
| 3                 | 1   | MANIFOLD ASSEMBLY   | READY ROBOTICS | R-101219    |
| 4                 | 1   | WISE ASSEMBLY       | READY ROBOTICS | R-101226    |
| 5                 | 1   | WISE ASSEMBLY       | READY ROBOTICS | R-101231    |



Pneumatic Block Diagram, Mill Tending

|  |                                                            |           |                      |                         |          |
|--|------------------------------------------------------------|-----------|----------------------|-------------------------|----------|
|  | READY Robotics<br>1080 Steelwood Rd.<br>Columbus, OH 43212 | SIZE<br>B | DO NOT SCALE DRAWING | DWG. NO.<br>PD-600009-2 | REV<br>- |
|  | DRAWN J. Miller                                            | ISSUED    | SCALE N/A            | SHEET 2 OF 2            |          |