




BILL OF MATERIALS				
ITEM	QTY	DESCRIPTION	MANUF.	PART NUMBER
1	2	BUTTONMATE ASSEMBLY	READY ROBOTICS	R-100103
2	2	PEDALMATE ASSEMBLY	READY ROBOTICS	R-100029
3	1	GRIPPER ASSEMBLY	READY ROBOTICS	R-101210




Pneumatic Block Diagram, Lathe Tending

 READY Robotics 1080 Steelwood Rd. Columbus, OH 43212	SIZE B	DO NOT SCALE DRAWING	DWG. NO.	REV -
			PD-600008	
DRAWN J. Miller	SCALE N/A	SHEET 1 OF 2		



BILL OF MATERIALS				
ITEM	QTY	DESCRIPTION	MANUF.	PART NUMBER
1	2	BUTTONMATE ASSEMBLY	READY ROBOTICS	R-100103
2	2	PEDALMATE ASSEMBLY	READY ROBOTICS	R-100029
3	1	GRIPPER ASSEMBLY	READY ROBOTICS	R-101210

Pneumatic Block Diagram, Lathe Tending

	READY Robotics 1080 Steelwood Rd. Columbus, OH 43212	SIZE B	DO NOT SCALE DRAWING	DWG. NO. PD-600008-2	REV -
	DRAWN J. Miller	ISSUED	SCALE N/A	SHEET 2 OF 2	